

Limited Ratings

<u>Rating</u>	<u>Manufacturer</u>	<u>Make / Model</u>	<u>Limitations</u>
	RAYTHEON	HAWKER 400 / 400 A	SHEET METAL REPAIR IAW SRM LIMITED TO P/N 128-590001-17.
	RAYTHEON	PREMIER 390 / 390 A	COMPOSITE REPAIR IAW SRM LIMITED TO P/N 390-590001-0019.
	RAYTHEON	HAWKER 400 / 400 A	COMPOSITE REPAIR IAW SRM LIMITED TO P/N 390-590001-0019.
	GROB	EGRITT G-520	COMPOSITE REPAIR IAW GROB DAMAGE ASSESSMENT AND REPAIR MANUAL.
	BELL HELICOPTER	206	COMPOSITE REPAIR
	BOEING	727	COMPOSITE REPAIR
	BOMBARDIER	CL-600 Series	COMPOSITE REPAIR
	BOMBARDIER	GLOBAL EXPRESS	COMPOSITE REPAIR
	CESSNA	CITATION 500, 501, 550,	COMPOSITE REPAIR
	CESSNA	551, 550B, 560	COMPOSITE REPAIR
	CESSNA	CITATION 525, 650	COMPOSITE REPAIR
	CESSNA	CITATION 560 XL	COMPOSITE REPAIR
	CESSNA	CITATION X 750	COMPOSITE REPAIR
	CIRRUS	SR20/SR22	COMPOSITE REPAIR
	DASSAULT / FALCON	FALCON 20	COMPOSITE REPAIR
	DASSAULT / FALCON	900, 900EX, 2000	COMPOSITE REPAIR
	DASSAULT / FALCON	F - 900	COMPOSITE REPAIR
	DIAMOND AIRCRAFT	DA 40 (DIAMOND STAR)	COMPOSITE REPAIR
	GULFSTREAM	ASTRA SPX	COMPOSITE REPAIR
	GULFSTREAM	GII, GIIIB, GIII, GIV, GV	COMPOSITE REPAIR
	LEAR JET	20, 30, 45, 55	COMPOSITE REPAIR
	MITSUBISHI	MU-2	COMPOSITE REPAIR
	RAYTHEON HAWKER	HS-125-1 thru 400	COMPOSITE REPAIR
	RAYTHEON HAWKER	600, 700, 800A, 800B, 800XP	COMPOSITE REPAIR
	RAYTHEON HAWKER	1000A, 1000B	COMPOSITE REPAIR
	SABRELINER	NA 265	COMPOSITE REPAIR

Limited Ratings - Specialized Services

<u>Rating</u>	<u>Specifications</u>	<u>Limitations</u>
TIG WELDING	AWS - D17.1	USE OF THE METHODS, TECHNIQUES, AND PRACTICES PRESCRIBED IN THE CURRENT MANUFACTURERS MAINTENANCE MANUAL, OR INSTRUCTIONS FOR CONTINUED AIRWORTHINESS, OR OTHER METHODS, TECHNIQUES, AND PRACTICES ACCEPTABLE TO THE ADMINISTRATOR.